

# Oil Field Environmental Incident Summary

**Incident:** 20150724143546      **Date/Time of Notice:** 07/24/2015 14:35

**Responsible Party:** DENBURY ONSHORE, LLC

**Well Operator:** DENBURY ONSHORE, LLC

**Well Name:** KING SWD SYSTEM D01

**Field Name:** SOUTH WESTHOPE

**Well File #:** 5150

**Date Incident:** 7/24/2015      **Time Incident:** 09:30

**Facility ID Number:**

**County:** BOTTINEAU

**Twp:** 162      **Rng:** 80      **Sec:** 24      **Qtr:**

**Location Description:** North of King TB 200 yds. In south ditch & north ditch of road. Impacted an area about 100 yards long in ditch full of cattails.

**Submitted By:** Josh Cuppy

**Received By:**

**Contact Person:** Rick Larson  
5320 LEGACY DR  
PLANO, TX 75024-3127

**General Land Use:** Other - Described Above

**Affected Medium:** Topsoil

**Distance Nearest Occupied Building:** 1 Mile

**Distance Nearest Water Well:** 1 Mile

**Type of Incident:** Pipeline Leak

**Release Contained in Dike:** No

**Reported to NRC:** No

	<b>Spilled</b>	<b>Units</b>	<b>Recovered</b>	<b>Units</b>	<b>Followup</b>	<b>Units</b>
<b>Oil</b>						
<b>Brine</b>	50	Barrels	50	Barrels	50	barrels
<b>Other</b>						

**Description of Other Released Contaminant:**

Also recovered 100 bbls of standing water from ditch area.

**Inspected:**

**Written Report Received:** 1/25/2016

**Clean Up Concluded:** 9/16/2015

**Risk Evaluation:**

NONE

**Areal Extent:**

100 yard long ditch area impacted.

**Potential Environmental Impacts:**

Standing surface water in ditches was impacted along with cattails.

**Action Taken or Planned:**

SHut in offending line. Recovered all standing fluids. Impacted area will be flushed with freshwater and recovered also.

**Wastes Disposal Location:** Basin SWD

**Agencies Involved:**

**Updates**

---

**Date:** 7/27/2015    **Status:** Reviewed - Follow-up Required

**Author:** Suess, Bill

**Updated Oil Volume:**

**Updated Salt Water Volume:**                      50.00 barrels

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Release left the pad and impacted water and cattails in a ditch. Follow-up is required.

---

**Date:** 7/30/2015    **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 12:30 7/30/2015. Pipeline has been exposed with the smell of produced water present. Impacted soil still on location and impacted water still present in ditches (area sampled). Visible dead grass in the un-excavated impact areas. A request was sent to the responsible party to vertically and laterally delineate the area. More follow-up is necessary.

---

**Date:** 8/17/2015 **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location 13:05 8/12/2015.

Excavated material hauled away, and excavation filled to grade.

Request all analytical results from the spill.

More followup is necessary.

---

**Date:** 10/30/2015 **Status:** Correspondence

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received limited investigation report for the site.

---

**Date:** 11/2/2015 **Status:** Correspondence

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Received summary report for the horizontal and lateral delineation of the site.

---

**Date:** 11/12/2015 **Status:** Inspection

**Author:** Stockdill, Scott

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

Arrived on location at 11/12/2015.

The excavation appears to have been filled, and the earth work appears complete.

Followup with company is deemed necessary depending on the contents of the summary report.

More followup is necessary.

---

**Date:** 7/25/2016 **Status:** Inspection

**Author:** Martin, Russell

**Updated Oil Volume:**

**Updated Salt Water Volume:**

**Updated Other Volume:**

**Updated Other Contaminant**

**Notes:**

7/25/2016 at 18:02, on location. Ditch where excavation occurred currently underwater. Follow-up next growing season; also dependent on summary report.